

SERVICE LETTER

SL-200C-051805

TO: ALL OWNERS / OPERATORS OF AFFECTED PROPELLERS
SUBJECT: PIN BASE REPLACEMENT (P/N 20006 REV B)
DATE: MAY 18, 2005

MODELS AFFECTED: All Whirl Wind 200C Series propellers manufactured before May 2005.

REASON: Propeller blade pin base may fail causing loss of pitch control and excessive vibration.

TIMELINE: Recommended to be performed immediately. Not recommended to fly with this propeller until SL-200C-051805 has been complied with.

DESCRIPTION OF REPLACEMENT:

1. Remove current blade pin bases (2) and replace with P/N 20006 Rev B Pin Base. Modify Pin Link to accept new ½" Pin Base. Must be performed for all affected propeller models.
2. **Who Can Do the Replacement:** This replacement can be performed by any certified propeller service center or by the Whirl Wind Aviation service center.
3. **Where to Obtain Replacement Parts:** Replacement pin bases available direct from Whirl Wind Aviation.